

### Revised Manifest Summary Report

**HALBERT BROTHERS**  
**HALBERT BROTHERS**

Manifest Date	Bates#	Manifest#	Quantity	Units	Gallons	Code	# Trips	Assessed (gl) Volume	
10/31/1986		86534753		2668.8	LBS		CMP		

Total Records: 1

Default Volume: 0

Total Waste Volume: 1.3344

**DISPOSAL PICK UP:**

State of California—Health and Welfare Agency

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of		Information in the shaded areas is not required by Federal law.						
3. Generator's Name and Mailing Address Halbert Bros. 2116 Sacramento St., Los Angeles, CA 90021						A. State Manifest Document Number <b>86534753</b>								
4. Generator's Phone (213/ ) 622-2331						B. State Generator's ID								
5. Transporter 1 Company Name Omega Recovery Services				6. US EPA ID Number CA DO 4 2 245 001		C. State Transporter's ID <b>501237</b>								
7. Transporter 2 Company Name				8. US EPA ID Number		D. Transporter's Phone <b>213/698-0991</b>								
9. Designated Facility Name and Site Address Omega Recovery Services 12504 E. Whittier Blvd. Whittier, CA 90602				10. US EPA ID Number CAD 042245001		E. State Transporter's ID								
						F. Transporter's Phone								
						G. State Facility's ID <b>CAD042245001</b>								
						H. Facility's Phone <b>213/698-0991</b>								
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers		13. Total		14. Unit		15. Waste No.		
						No. Type		Quantity		Wt/Vol				
a. Hazardous Waste, Liquid NOS ORM-E NA 9189 (Lithium Bromide)						007 DM		0032.0		G				
b.														
c.														
d.														
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above								
15. Special Handling Instructions and Additional Information Pick up 3 empty drums that were not needed. Facility located near Santa Fe and 7th St. FW														
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.														
Printed/Typed Name DE L HALBERT					Signature <i>De L Halbert</i>					Month Day Year 11/03/86				
17. Transporter 1 Acknowledgement of Receipt of Materials										Month Day Year				
Printed/Typed Name ISAAC WOODS JR					Signature <i>Isaac Woods Jr</i>					Month Day Year 11/03/86				
18. Transporter 2 Acknowledgement of Receipt of Materials										Month Day Year				
Printed/Typed Name					Signature					Month Day Year				
19. Discrepancy Indication Space														
20. Facility Owner or Operator. Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.														
Printed/Typed Name FRANK FORD					Signature <i>Frank Ford</i>					Month Day Year 11/03/86				

DHS 8022 A (11/85)  
(EPA 8700-22)

White: TSDf SENDS THIS COPY TO DOHS WITHIN 30 DAYS  
To P @ Box 3000, Sacramento CA 95812

04/25/2000 "ORIGINAL MANIFEST COPY"